

1


What would correct the observed abnormality:

1. Increase V pacing output
2. Make V more sensitive
3. Increase V pacing rate
4. Lengthen the AV interval

***Pay attention to what the device tells you,
but pay equal attention to what it "doesn't"
tell you!***

BIOTRONIK
Sustained for life

2



What would correct the observed abnormality:

1. Increase V pacing output
2. Make V more sensitive
3. Increase V pacing rate
4. Lengthen the AV interval

***Pay attention to what the device tells you,
but pay equal attention to what it "doesn't"
tell you!***



3




The programmed P-AVI is 240 ms. Labeled QRS complex (*) occurs in:


1. Crosstalk sensing window
2. Post-Atrial Ventricular blanking period
3. Alert window




4



5



6



Inspect for patterns

ECG following dual-chamber pacemaker implant suggests?

BIOTRONIK
accelerated for life

7

83-Year-Old Male with Increasing Dyspnea on Exertion

- History of coronary artery disease status post stent placement $\times 2$
- Third-degree AV block, status post pacemaker placement 8 years earlier (Medtronic dual-chamber Kappa KDR 901, atrial lead 5568, ventricular lead 4076)
- Programmed DDDR, lower rate 60 bpm, upper rate 130 bpm

8

BIOTRONIK
accelerated for life

8




Prior to pacemaker interrogation, rhythm was ventricular pacing at 65 bpm. This tracing obtained when the programming wand is placed on the pacemaker. Tracing can be explained by:

1. Conductor coil completely fractured
2. ERI (Elective replacement indicator)
3. EOS (End of service)
4. Ventricular lead loose in header



9




10



10

Pacemaker Model: Medtronic Kappa KDR901	Medtronic Kappa 900 S
Serial Number:	Copyright © Medtronic
Initial Interrogation Report	
Patient/Device Information	
Dependency:	Physician Name:
Implanted Defibrillator?:	Physician Phone:
Pacemaker Model: Kappa KDR901 PKM418309	Implanted: 07/17/15 6:49 PM
Atrial Lead:	
Ventricular Lead:	
Pacemaker Status	
Estimated remaining longevity: Replace Pacer	
Battery Voltage/Impedance: 2.06 V / 32,125 ohms	
Amplitude/Pulse Width	2.76 V / 0.40 ms
Sensitivity	2.00 mV
Measured Impedance	680 ohms
Lead Status	Polarity Switch
Clinical Status:	
Diagnostic data not available.	

11




11

83-Year-Old Male with Increasing Dyspnea on Exertion

- Battery voltage of 2.06 is compatible with EOS (EOL), at which point no reliable pacing occurs and diagnostic information is unreliable. It is difficult for manufacturers to give a single specific voltage at which EOS occurs because of multiple variables that may be present
- For this old Medtronic device, the company states that a measured battery voltage of 2.2 is a reasonable value to consider for EOS, but some devices may reach EOS at a higher value, and some have been identified at <2.0 V before
- Battery impedance is often ignored. In this case, the battery impedance was 32,125 ohms. As a rule, if battery impedance is $\geq 10,000$ ohms, there should be a heightened concern that battery is approaching EOS. If battery impedance is $\geq 20,000$ ohms, there is a high likelihood the device is at or near EOS.

12



12



Pacemaker Troubleshooting: A case-based approach

David Hayes, MD




13

Goals:

1. Address one of the most commonly confusing concepts in brady pacing
2. How to approach an unknown – beat by beat
3. Moving from a 'generic' diagnosis to a specific etiology
4. To be specific with terminology

14 FEBRUARY 20, 2024



14

Device Electrocardiography

Need to know and understand differential diagnoses of each of the following:

- Failure to sense
- Failure to capture
- Failure to output/oversensing
- Rate variations
- Crosstalk / safety pacing

15 | FEBRUARY 20, 2024 |

BIOTRONIK
INDEPENDENCE FOR LIFE

15


DDDR 60-140, AV delay 220 msec, V-A interval (AEI) @ LRL: 780 ms




16 | FEBRUARY 20, 2024 |

BIOTRONIK
INDEPENDENCE FOR LIFE


16



17



18



19

Crosstalk

VSP doesn't eliminate crosstalk – it prevents asystole

- Unwanted detection in one channel of a signal from another channel
- Most common: afterpotential from atrial output sensed by V channel and resets VA interval
- AV crosstalk easier to avoid with bipolar sensing configuration, less sensitive to far-field signals


May be eliminated by:

- ↑ the blanking period (so that ventricular sensing resumes later)
- ↓ the atrial stimulus voltage or duration (if adequate safety margin can be maintained)
- Make ventricular channel less sensitive


20 FEBRUARY 20, 2024

BIOTRONIK

20




21



22

Pacemaker programmed to DDI 86 ppm; AVI = 165 ms; PVAB = 13 ms. Referred with ? of abnormal PM function

Note – all A activity is paced & all V activity is intrinsic



The most appropriate approach would be:


1. Lengthen PVARP
2. Lengthen PVAB
3. Lengthen AVI
4. Lower the upper rate limit

23 | FEBRUARY 20, 2024 |

BIOTRONIK
INDEPENDENCE FOR LIFE

23

Determining the VA Interval




- $VV = AV + VA$
- $VV - AV = VA$
- Programmed VV = 86 ppm = 697 ms
- AV = 165 ms
- $697 - 165 = 532$ ms (VA)

24 | FEBRUARY 20, 2024 |

BIOTRONIK
INDEPENDENCE FOR LIFE

24



- Measured RR = 575 ms = VV
- $575 - 532$ (VA) = 43 ms (AV)
- Point of sensing after atrial output is 43 ms
- Blanking period of > 43 ms should avoid crosstalk

25 | FEBRUARY 20, 2024 |

25

After lengthening the ventricular blanking period to > 43 ms the tracing is compatible with programming, i.e. rate 86 bpm, AVI 165 ms




26 | FEBRUARY 20, 2024 |

26

Based on your ECG diagnosis you would:

Always ask:

1. Single or dual
2. Underlying rhythm
3. Obvious pacing mode
4. Measurable intervals




27 | FEBRUARY 20, 2024 |



27

1. Make ventricular channel more




28 | FEBRUARY 20, 2024 |




28

- The abnormality that must first be recognized is intermittent ventricular undersensing. However, the presence of 'Autocapture' with backup pulses results in a confusing tracing. Furthermore, functional failure to capture may make it even more confounding.
- The Autocapture backup pulse is delivered at approximately 80 ms after the initial output. The appearance is that of intermittent loss of capture followed by backup pulses that do capture as long as the myocardium is not refractory. The device times off of these backup pulses, resulting in irregular intervals between captured complexes.
- Once a diagnosis of intermittent ventricular undersensing is made, the only possible correct answer of those listed is to correct the fundamental problem by making the ventricular channel more sensitive.

Routine visit 3 months post DDDR implant; programmed DDD mode AVI-P – 175 ms; AVI-S – 150 ms



Routine visit 3 months post DDDR implant; programmed DDD mode AVI-P – 175 ms; AVI-S – 150 ms



Your initial observation leads you to which of the following general diagnostic categories?

1. Ventricular failure to capture
2. Ventricular failure to output
3. Ventricular true undersensing
4. Ventricular functional undersensing

31



In the clinic with the patient, which of the following would help narrow your differential diagnosis?

1. Program to AAI
2. Magnet application
3. Disable rate-adaptive pacing
4. Lengthen the AVI

32

Magnet Application



33 | FEBRUARY 20, 2024 |

33

Measured Data

Ventricular

- Pulse amplitude 4.1 V
- Pulse current .2 mA
- Pulse energy 0
- Pulse charge 0
- Impedance > 3000

Atrial

- Pulse amplitude 3.8V
- Pulse current 9.6 mA
- Pulse energy 12
- Pulse charge 4
- Impedance 398

34 | FEBRUARY 20, 2024 |

34



35 | FEBRUARY 20, 2024 |

35


Which of the following could explain the abnormality noted?

1. Exit block
2. Ventricular lead dislodgement
3. Loose set screw
4. Ventricular oversensing

36 | FEBRUARY 20, 2024 |

36

1. Exit block – *would result in failure to capture NOT failure to output and artifacts would have been present with magnet*
2. Ventricular lead dislodgement - *would result in failure to capture NOT failure to output and artifacts would have been present with magnet*
- 3. Loose set screw**
4. Ventricular oversensing – *Although this could present as failure to output or inhibition, it would be unlikely to be as regular as noted on the non-magnet tracing and magnet would have forced pacing artifacts*



Rhythm strip obtained the afternoon after the pacemaker implant. Patient asymptomatic. Generic diagnosis?

1. Failure to capture
2. Failure to output
3. Undersensing
4. Rate variation



39 | FEBRUARY 20, 2024 |

39

Failure to Output

- Oversensing
 - Crosstalk
 - EMI
- Battery failure
- Circuit failure
- Lead fracture
- Internal insulation failure
- Loose set-screw
- Incompatible lead/header
- Pseudomalfuction, i.e. device nuance

40 | FEBRUARY 20, 2024 |

40

If intervals are regular and baseline steady, less likely to be oversensing.



41 | FEBRUARY 20, 2024 |

41

Failure to Output


- ~~Oversensing~~
 - ~~Crosstalk~~
 - ~~EMI~~
- ~~Battery failure~~
- ~~Circuit failure~~
- ~~Lead fracture~~
- ~~Internal insulation failure~~
- ~~Loose set screw~~
- ~~Incompatible lead/header~~
- ~~Pseudomalfuction, i.e. device nuance~~

42 | FEBRUARY 20, 2024 |

42

Engineering explanation:

- An occasional 'dropped VP' is specific to DDDR and DDD modes during atrial tracking (AS-VP) and may occur intermittently on an hour and 30 s schedule.
- A false ventricular sense may occur due to residual electrical disturbance on the ventricular sense amplifier and may be created by turning on/off the diagnostic EGM amplifiers during reference EGM collection. The scheduled reference EGM collection is synchronized to sensing and pacing events so that the device's sense amplifiers are blanked. However, there is no ventricular blanking following an AS event, which makes this phenomenon possible. The collection of reference EGM is non-programmable and is always active in the device.



Mehra, et al. Europace e-Pub April 16, 2015
43 | FEBRUARY 20, 2024 |



43


16 yo female with intermittent CHB

- Paced 2 years earlier for CHB
- Local basketball star--good chance of getting college scholarship to play
- Presents with intermittent exertional lightheadedness


44 | FEBRUARY 20, 2024 |




44



45



46



47

You would:

1. Observe
2. Holter to determine frequency of abnormality
3. Replace ventricular lead

What advice would you give regarding activities?

48

© 2024 BIOTRONIK, Inc. All rights reserved. PPT_EDU_013_Pacemaker_Troubleshooting 2/20/2024

BIOTRONIK

48


Sudden Fatigue During Exertion

You would perform:


1. V-stim
2. Tilt-table testing
3. Exercise test
4. Coronary angiogram




49



50



51



52



53



54

Approach to Paced ECG in Clinic or on Exam

- Carefully assess the clinical question
 - Determine important components
 - Ignore extraneous information
- Utilize all diagnostics available
- Assess tracing left to right and also horizontally
- Make 'generic' diagnosis
- Consider differential diagnosis for generic etiology