


1



2

CIED Diagnostics

- There are extensive and increasingly sophisticated diagnostics in contemporary devices
- Diagnostics are critical for determination of normal or abnormal device function
- A deep understanding of the diagnostics available from the manufacturer(s) implanted at your institution is invaluable
- In the clinical environment you will have the benefit of the patient's clinical information and programming – this talk purposefully approaches diagnostics without providing the benefit of all the usual information in the effort to develop a framework for a systematic approach

Device Troubleshooting: CRT builds on ICD builds on Brady

Approach brady devices with simple steps:

- What's the underlying rhythm?
- Single vs dual-chamber pacing?
- Which chamber(s)?
- Identifiable timing intervals?
- Make a "Generic" Diagnosis
- Target specific dx based on clinical scenario for that generic differential diagnosis

Troubleshooting Steps to Consider: Brady

- Try other pacing modes to overcome a problem, i.e. start with simplest (VVI) and proceed from there
- Telemetry: EGMS, marker channel etc.
- Patient Postural Testing
- Chest x-ray
- Technical manual
- Call manufacturer 24 hour support number (1-800-547-0394)
- Intraoperative troubleshooting

Pacing Electrocardiography

Need to know and understand differential diagnoses of each of the following:

- Failure to sense
- Failure to capture
- Failure to output/over-sensing
- Rate variations
- Crosstalk / safety pacing

Loss of Capture

Less Common

- Loose set-screw
- Exit block
- Perforation
- Battery failure
- Circuit failure
- Air in pocket (Unipolar)
- Pseudomalfuction
- Metabolic/drug

More Common

- Lead dislodgment
- Elevated thresholds
- Inappropriate lead placement
- Lead fracture
- Lead insulation failure

7

JANUARY 31, 2024



7

Failure to Output

Less Common

- Loose set-screw
- Lack of anodal connector contact
- Incompatible lead/header
- Pseudomalfuction or device nuance - peculiarity

More Common

- Over-sensing
- Crosstalk
- EMI
- Battery failure
- Circuit failure
- Lead fracture
- Internal insulation failure

8

JANUARY 31, 2024



8

Under-Sensing

- Change in intrinsic complex, i.e. BBB, VF, VT, AF
- Myocardial infarction
- Lead dislodgment/poor positioning
- Lead insulation failure
- Magnet application
- ERI
- Functional under-sensing

Over-Sensing

- Lead fracture
- Lead insulation defect
- EMI
- Isoelectric ventricular event
- Sensing T wave, P wave, afterpotential, etc


Rate Variations (i.e. variations from programmed lower rate)

- Hysteresis
- Rate-adaptive pacing
- Oversensing
- Function of timing system, i.e. AA, VV, hybrid
- Specific Algorithms, i.e. Capture Control, Night Rate, etc.

11 JANUARY 31, 2024

 **BIOTRONIK**
excellence for life

11




- 3.1 The tracing includes:
1. Intrinsic beat
 2. Paced beat
 3. Fusion beat
 4. Pseudofusion beat
 5. All of the above

12 JANUARY 31, 2024

 **BIOTRONIK**
excellence for life

12




3.3 Tracing demonstrates all BUT:

1. Atrial pacing
2. Atrial sensing
3. Ventricular pacing
4. Atrial event in refractory
5. Ventricular event in refractory

15 JANUARY 31, 2024

BIOTRONIK
 excellence for life

15




3.4 Tracing compatible with:

1. Appropriate mode-switching
2. Far-field sensing
3. Pacemaker mediated tachycardia
4. Normal rate-adaptive pacing

16 JANUARY 31, 2024

BIOTRONIK
 excellence for life

16




3.5 Tracing compatible with:

1. Functional under-sensing
2. Far-field sensing
3. Crosstalk
4. Pacemaker mediated tachycardia

17 JANUARY 31, 2024

BIOTRONIK
excellence for life

17




3.6 66 year old female 1 wk post-implant. The only compatible etiology of the problem is:

1. Crosstalk
2. Ventricular lead dislodgment
3. Ventricular avoidance pacing algorithm
4. Ventricular oversensing
5. Exit block

BIOTRONIK
excellence for life

18



3.7 1 year after PPM, uneventful to date, patient presents with recurrent syncope. Etiology could be all but which of the following:

1. Exit block
2. Threshold increase secondary to medications
3. Lead dislodgment
4. Complete fracture of the ventricular lead conductor coil

19 JANUARY 31, 2024

BIOTRONIK
excellence for life

19

1 year post PPM; uneventful to date

Presents with recurrent syncope. All but which of the following could be responsible:


1. Exit block - > 1 month post-implant with failure to capture is compatible with exit block; would not likely occur at 1 year; usually earlier
2. Threshold ↑ secondary to medications - failure to capture is compatible
3. Lead dislodgement - compatible with failure to capture
4. Complete break of the conductor coil - with complete transection, current would not get through and no artifact would be seen

20 JANUARY 31, 2024

BIOTRONIK
excellence for life

20


What is occurring at the arrow?



21 JANUARY 31, 2024

BIOTRONIK
 excellence for life

21




3.8 What is your ECG diagnosis?

1. Hysteresis
2. Over-sensing retrograde events
3. Fallback behavior
4. Normal sensor-driven pacing

22 JANUARY 31, 2024

BIOTRONIK
 excellence for life

22



What is your ECG diagnosis?

1. Hysteresis
2. Over-sensing retrograde events
3. Fallback behavior
4. Normal sensor-driven pacing

23 JANUARY 31, 2024

BIOTRONIK
excellence for life

23

3.9 The ECG is obtained the morning after pacemaker implant. Which of the following is the most likely problem?


1. Crosstalk in absence of safety pacing
2. Ventricular lead dislodgment
3. Artifact
4. Ventricular lead fracture
5. Myopotential over-sensing



24 JANUARY 31, 2024

BIOTRONIK
excellence for life

24




3.10 What would correct the observed abnormality:

1. Increase V pacing output
2. Make V more sensitive
3. Increase V pacing rate
4. Lengthen the AV interval

*Pay attention to what the device tells you,
but pay equal attention to what it "doesn't"
tell you!*

25



What would correct the observed abnormality:

1. Increase V pacing output
2. Make V more sensitive
3. Increase V pacing rate
4. Lengthen the AV interval

*Pay attention to what the device tells you,
but pay equal attention to what it "doesn't"
tell you!*

26

3.11 The programmed P-AVI is 240 ms. Labeled QRS complex (*) occurs in:

1. Crosstalk sensing window
2. Post-Atrial Ventricular blanking period
3. Alert window




27 | JANUARY 31, 2024

excellence for life

27

If the event occurs in the crosstalk sensing window is sensed, the V is paced after an abbreviated AVI (light orange), falling in the physiologic refractory period, ie, does not fall in the vulnerable period

If the event occurs in the post-atrial ventricular blanking period, the sensing circuit is turned 'off' and the event is not seen (dark orange)




If sensing occurs during the 'alert' period, ventricular output is inhibited.

28 | JANUARY 31, 2024


excellence for life

28



29

ECG following dual-chamber pacemaker implant suggests?



30 JANUARY 31, 2024

BIOTRONIK
excellence for life

30


83-Year-Old Male with Increasing Dyspnea on Exertion

- History of coronary artery disease status post stent placement ×2
- Third-degree AV block, status post pacemaker placement 8 years earlier (Medtronic dual-chamber Kappa KDR 901, atrial lead 5568, ventricular lead 4076)
- Programmed DDDR, lower rate 60 bpm, upper rate 130 bpm

31 JANUARY 31, 2024

 **BIOTRONIK**
excellence for life

31




3.12 Prior to pacemaker interrogation, rhythm was ventricular pacing at 65 bpm. This tracing obtained when the programming wand is placed on the pacemaker. Tracing can be explained by:

1. Normal magnet function for this pacemaker
2. ERI (Elective replacement indicator)
3. EOS (End of service)
4. Ventricular lead loose in header

32 JANUARY 31, 2024

 **BIOTRONIK**
excellence for life

32



33

Pacemaker Model: Medtronic.Kappa KDR901
Serial Number: _____

Medtronic.Kappa 900 S
Copyright © Medtronic

Initial Interrogation Report

Patient/Device Information

Dependency:	Physician Name:
Implanted Defibrillator?:	Physician Phone:

Pacemaker Model: Kappa KDR901 PKM418309 Implanted: 07/17/15 6:49 PM
Atrial Lead:
Ventricular Lead:

Pacemaker Status

Estimated remaining longevity: Replace Pacer
Battery Voltage/Impedance: 2.06 V / 32,125 ohms

Ventricular

Amplitude/Pulse Width	2.76 V / 0.40 ms
Sensitivity	2.00 mV
Measured Impedance	680 ohms
Lead Status	Polarity Switch

Clinical Status:

Diagnostic data not available.

BIOTRONIK
excellence for life

34

83-Year-Old Male with Increasing Dyspnea on Exertion

- Battery voltage of 2.06 is compatible with EOS (EOL), at which point no reliable pacing occurs and diagnostic information is unreliable. It is difficult for manufacturers to give a single specific voltage at which EOS occurs because of multiple variables that may be present
- For this old Medtronic device, the company states that a measured battery voltage of 2.2 is a reasonable value to consider for EOS, but some devices may reach EOS at a higher value, and some have been identified at <2.0 V before
- Battery impedance is often ignored. In this case, the battery impedance was 32,125 ohms. As a rule, if battery impedance is $\geq 10,000$ ohms, there should be a heightened concern that battery is approaching EOS. If battery impedance is $\geq 20,000$ ohms, there is a high likelihood the device is at or near EOS.

Paced ECG Interpretation: A Case-Based Approach

David Hayes, MD